

Annexure D

BUILDING SAFETY CERTIFICATE

No. 030425

Dated: 03-04-2025

It is certified that the existing building THE CARNATION SCHOOL (name of the building or premises) at GHAMMUWALA, RANIPOKHARI, D. DUN.

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G. FLOOR F. FLOOR	G. FLOOR -	G. FLOOR F. FLOOR	-	-	-

The building is owned/occupied by THE CARNATION SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (Name of Department/ Govt.) on 02-04-2025 (date of inspection) in the presence of RATNEESH KUMAR (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 03-04-25 for a period of 10 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 03-04-2025 at PWD, DEHRADUN by Asst. Engineer (PWD).

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : Anil Kumar Singh Bishr

Name : Anil Kumar Singh Bishr

Designation : Asst. Engineer

Name & Address of Department/ Office: NH RD D. D. Wala